

# ecology and environment, inc.

108 SOUTH WASHINGTON, SUITE 302, SEATTLE, WASHINGTON 98104, TEL. 206-624-9537

International Specialists in the Environmental Sciences

September 21, 1982

TO: Bruce Zaczynski, NPMO

FROM: Thomas Tobin, RSC

Region X FIT

SUBJ: Site Safety Plan for Sampling

USDA Agriculture Experimental Laboratory

Yakima, WA

REF: TDD 10-8208-07

Enclosed is the site safety plan for installing a well point and sampling groundwater at the USDA Agriculture Experimental Laboratory in Yakima, WA (see attached figures).

As we discussed over the phone, and with your approval, the sampling team was in level D protective clothing at this site as they were doing environmental sampling. The laboratory is out in the open and as the sampling team would not be drilling through the drain field, there is minimal respiratory risk to Hussein and Larry. (As it turned out, the sampling team drilled down 20 feet and never encountered any groundwater and/or contaminated water and soil. Technically, they drilled through clean soil and did not collect any samples.) APRs and Robertshaw were available. Neither Hussein or Larry reported any problems.

Safety clothing and equipment (see attachment) were packed in an ice chest that the team took with them. They also carried an abbreviated safety plan listing emergency phone numbers and HSR data. Safety clothing (work boots, hard hats) were wiped off before being returned to the ice chest. Coveralls and work gloves were removed at the site. Water for cleaning and drinking was brought to the site by the sampling team. Disposable items were bagged and returned to Seattle.

Attachments TT:jq

usda-s FIT/16





# ecology and environment, inc.

108 SOUTH WASHINGTON, SUITE 302, SEATTLE, WASHINGTON 98104, TEL. 206-624-9537

International Specialists in the Environmental Sciences

# MEMORANDUM

DATE: 7/8/82

SUBJ: Yakima Agricultural Research

Laboratory, U.S.D.A.

TO: John Osborn

REF: TDD 10-8206-01

FROM: Jacqueline Betz (M)

CC: Phil Wong

# 1.0 SUMMARY

The U.S. Department of Agriculture's Research Laboratory in Yakima, Washington, has been researching pesticides since 1961. Many unknown formulations of pesticides are analyzed and consequently disposed of in a septic tank that has a drainfield system.

Because the geology of the area is characterized by sands and gravels with high permeability, there is concern that pesticides may be leaching into the drinking water aquifer.

The Field Investigation Team (FIT) conducted a preliminary site investigation on June 24, 1982. The plant manager was (b)(6) and no one was knowledgeable about the history of pesticide disposal methods and no maps were available to indicate the exact location of the drainfield system at the time. An HNU photoionizer, placed in shallow holes south of the septic tank dug by the FIT detected volatile organics in the soil above the background level. These volatile compounds were thought to be from the petroleum carrier solution mixed with the pesticides.

# 2.0 PHYSICAL DESCRIPTION

#### 2.1 LOCATION

The U.S. Department of Agriculture's Research Laboratory, 3706 West Nob Hill Blvd., Yakima, Washington 98902, is located within the city limits of Yakima in Section 27, Range 18 East, Township 13 North, Yakima West Quadrangle: Latitude 46°36'57", Longitude 120°33'37" (see Figure 1). The area is zoned for mixed use (commercial, residential, industrial).

#### 2.2 CLIMATE AND WATER BUDGET

According to the <u>Climatic Atlas of the United States</u> (U.S. Department of Commerce, 1968) this area receives approximately 8 inches of total precipitation annually with a mean annual lake evaporation of 42 inches. Approximately 75 percent of the precipitation falls in the period October through March.

The area is characterized by a dry continental climate because it lies in the rain shadow of the Cascade Mountain Range. The hottest months are June-August with temperatures as high as 100°F. The coolest months are December-February with minimum temperatures in the 20's F.

#### 2.3 GEOLOGY AND HYDROLOGY

Well logs indicate the immediate area is underlain by a sandy gravelly loam on top of a cemented sand and gravel referred to in some well logs as conglomerate. Soil permeability is high and slopes are low (<2%). Water yields in these gravels is relatively low but adequate for domestic needs. The major aquifer is in the Yakima basalt at depth (Foxworthy, 1962).

The water table is shallow (<20 feet), mainly because of extensive irrigation in the area during the summer, and also influx from creeks draining the mountains. Groundwater flow is to the southeast towards the Yakima River.

Well logs for domestic wells are not required by the County of Yakima, therefore, groundwater use in the vicinity cannot be quantifed. However, there are some well logs filed that indicate shallow wells downgradient are presently being used for private domestic purposes (see Well Logs, Attachment A). The primary use of groundwater in this area is for irrigation. Public water is supplied by the City of Yakima from the Naches River.

#### 2.4 LAND USE AND SENSITIVE HABITATS

The area surrounding the site is within metropolitan Yakima. More than 10,000 people live within a mile of the site. According to the U.S. Fish and Wildlife Service (USFW) no known threatened or endangered species inhabit this area. It is not registered as a critical habitat by the USFW.

#### 3.0 DISPOSAL PRACTICES

The research facility generated little waste from its beginning in 1961 through 1968 according to B. Brown, Administrative Officer. Wastes from 1961 through 1968 were disposed of on the ground. About 1968 the septic tank and drainfield system were installed to dispose of unused mixed pesticides from spray application equipment, wastes from a mixing formulation laboratory and rinse water from spray application equipment. A sink and toilet also drain into the 300 gallon septic tank.

The USDA estimates that about 250 gallons of mixed pesticides and about 5000 gallons of rinsate from the application equipment are injected into the septic tank each year.

## 4.0 PRELIMINARY SITE INVESTIGATION

On June 24, 1982, the FIT visited the site with Dennis Bowhay, Washington State Department of Ecology. An HNU photoionizer, used to check for organics in the soil, showed several readings above the background level in the area to the south of the septic tank (see attached maps of the facility). There was a slight chemical odor. The cement drain for the septic tank was in active use while the FIT was on site (see photographs, attached).

## 5.0 DISCUSSION


About 250 gallons of mixed pesticides and 5000 gallons of rinsate has been disposed of annually for the last 14 years at this site. It is assumed that some of these pesticides are toxic and persistent and pose a threat to human health and the environment. There is the possibility of offsite migration of pollutants into the unconfined aquifer, used downgradient for private domestic drinking water wells.

## 6.0 CONCLUSIONS AND RECOMMENDATIONS

Unknown formulations of mixed pesticides are likely to be leaching into the groundwater and migrating offsite. The FIT recommends that domestic wells in the area be sampled and analyzed for priority pollutants and pesticides. An upgradient domestic well could be used as a monitoring well and a minimum of two downgradient wells onsite should be installed to determine what migration may be taking place.

#### REFERENCES

- Foxworthy, B.L., 1962, Geology and groundwater resources of the Ahtanum Valley, Yakima County, WA. U.S. Geological Survey, Water Supply Paper 1598.
- U.S. Geological Survey (USGS), 1958, (photorev. 1974) Yakima West, WA.: National Topography Map Series, Scale 1:24,000.



YAKIMA AGRICULTURAL RESEARCH LABORATORY, YAKIMA, WA

# WATER WELL REPORT

STATE OF WASHINGTON

Application No.

Permit No

(b)(6)	E OF W	MSBLING TUN	_	Permit No	
(1) OWNER: Name		(b)(6)		Gabine, 1:	rew.
(2) LOCATION OF WELL: County	izne		SIUN SENSE	27 T. 1.3 N. R.	18 W.M
L ig and distance from section or subdivision corner					
(3) PROPOSED USE: Domestic X Industrial   Muni	icipal []	(10) WELL LO	G:		
Irrigation   Test Well   Other	- 1	Formation: Describe	by color, character, si	ze of material and stra	icture, and
/// TYPE OF WORK- Owner's number of well		show thickness of aq	pulfers and the kind or	nd nature of the mater by for each change of	ial in each
(4) III of World (if more than one)	ored D		MATERIAL	FROM	TO
	riven 🛛	- Japa	Soil.	0	10
Reconditioned	tted 🗆	Corne	Con le	10	58
(5) DIMENSIONS: Diameter of well 5. Depth of completed well. 5.8	inches. ft.				
(6) CONSTRUCTION DETAILS:					
Casing installed: 5 - Diam from C 11. to 28	' /c'',				1
Threaded   "Diam. from = ft. to			1-1		1
Welded "Diam. from ft. to	. ft.		W		
Perforations: Yes D No X					
Type of perforator used					
SIZE of perforations in by perforations from the fit to	1	1			
perforations from the fit to					
perforations from ft to	1t.	(b)(6)			
Screens: Yes D No W					
Manufacturer's Name		-		0	,
7 Model No		5			
Diam Slot size from ft. to		~			
Crowd walled: u. c. u. c.					
Gravel packed: yes No No Size of gravel					
Surface scal: Yes X No D To what depth?  Material used in scal Denterial.	ft.				
Did any strata contain unusable water? Yes 🔲 😁		2200			
Type of water? Depth of strata	1	1.1.11			
Method of sealing strata off	10.000	1 ( -			
(7) PUMP: Manufacturer's Name		· PA	17 1981		
Type: H.P.					
(8) WATER LEVELS: Land-surface elevation CAP. 11	C Cn.		5		
Static level 7 4 ft below top of well Date 2 -/-	2-81		_		
Artesian pressure lbs. per square inch. Date					
(Cap, valve, etc.)					
(9) WELL TESTS: Drawdown is amount water level is lowered below static level	1		-/2 1981 Com	npleted Z - /2	. 1.81
Was a pump test made? Yes 🗇 No 🔘 If yes, by whom?	1.	Work started. 👟			11171
Yield: 2 C gal/min with ft drawdown after	hrs		R'S STATEMEN		
" W/266264 V		This well was d true to the best of	lrilled under my ju ' my knowledge an	risdiction and this d belief.	report is
Recovery data (time taken as zero when pump turned off) (water					
rieasured from well top to water level)  Time Water Level   Time Water Level   Time Water	Level 2	NAMEJENSE	NS WELL DR	ILLING + DRI	MIN
		1/ / n	rson, firm, or corporat	tion) (Type or pr	int)
	- 4	Address. 16.6.5	JOHN AVE	YAKIMA,W	ASH.
	11100 P	$\alpha l^{2}$	in A A	0	
e of test  Bailer test gal /min with ft drawdown after	. hrs.	[Signed]	(Well I	Driller)	<b>1</b>
Artesian flow g.p.m. Date g.p.m.	1	0 5	)   7	ie 3 - 12	81
Temperature of water DE Was a chemical analysis made? Yes []	No X	ucense No	Da	ite	. 19 V.L.

Copy Owner's Copy Driller's Co		STATE OF W	ASHINGTON		Parmis No.	/	
(I) OWNED.	(b)(6)		(b)(6)		Permit No		lling
(1) OWNER: Name			Address .	71 7 5:111			
	m section or subdivision corner		11-8'0171	-71E 1 SW 1 Sec 243.18 5807		JN., R.⊿ ♥	(d' w.m.
	SE: Domestic 🌠 Industria	/	(10) WELL 1				
, THOTOBBB C.	Irrigation [] Test Wel		Formation: Descr	ibe by color, character, siz	e of material	and stru	cture, and
(4) TYPE OF WO	RK. Owner's number of wel		stretum penetrete	cquifers and the kind and colors with at least one entry	g neture of the for each ch	lange of j	al in each formation.
Ne	w well K Method: Dug	Bored 🖸	7	MATERIAL		FROM	44.
	. –	ole   Driven     lary   Jetted		PAVALL		"	7
(5) DIMENSIONS:	Diameter of well	6inches.	Hard	sand gran	elda-pu	4	34
Drilled . 65	ft. Depth of completed we		Sands	toni Illand	21/23	34	5%
(6) CONSTRUCTION	ON DETAILS:		· · · ·	1.1	1	-	***
Casing installed	d: # " Diam. from	_ ft. to 40 ft.	Mindel	mid alleria	15% 1.4		
Threaded [] Welded 72	" Diam. from" Diam. from"		quelle le	celer	7	51	65
Perforations: Y	es   No XI rator used	der en tuder om enskapen i saan, ji kaanspe					
•	rations in. by					1	
•	erforations from ft.						
pe	riorations from ft.	. to					
Screens: Yes 🗆	No 💢						
	Name Model						
D:am	Slot size from from	ft. to ft.				-	
	Siot size from	ft. to ft_					
Gravel packed:		vel:					
	from ft. to	-10				!	
	in seal Distlement						
Did any strata	a contain unusable water?	Yes 🗆 No 🔀					
	Depth of str						:
Type:	urer's Name	нР					
(8) WATER LEVE	S: Land-surface elevation			*			
	above mean sca levelft. below top of well D	ale 29-11-74					
·		i i					
Artevian water	is controlled by(Cap, 1	valve, ctc.)					
(9) WELL TESTS:	Drawdown is amount wa lowered below static lev		Work started, 29	-71 -74	pluted 29	-77 <sup>1</sup>	71/
111	es   No   If yes, by whom			LER'S STATEMENT			4 134 1
	with st drawdown as	// hrs.		s drilled under my jur		ad this r	enert is
			true to the best	of my knowledge and	belief.	id this t	eport 15
Recovery data (time take measured from well to	n as zero when rump turned p to water level)	1	1 / C	The Sh	4//	in 1	11C
Time Water Level	Time Water Level Time	Water Level	NAME . (	(Person, firm, or corporati	on) (Ty	pd or pri	nt)
			Address-2:20	2-11www.	Makin	ulli	?(
	······································		166	T. 11/9	1.7		
Pate of test	n. with ft drawdown	after hrs.	[Signed]	(Well D	riller)	:	
sesian flow	Was a chemical analysis ma		License No	112	201_	11	10/4
temperature of water	was a chemical analysis ma	Mou te C vo M		,4	٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠	·/	, 13./[

# WATER WELL REPORT

STATE OF WASHINGTON

Application No. U. 3-20531

Permit No. . G 3-20651 P

129

145

147

חווים נקטש וכנו ביי וה יהו il of Redogy

il of Redogy

Owner's Copy

Init'd Copy — Driller's Copy (1) OWNER: Name City of Yakima (2) LOCATION OF WELL: County Yaking nd distance from section or subdivision corner N. 500 W 320' from SE cor. SWZSWZ (2) PROPOSED USE: Domestic [] Industrial [] Municipal [] Irrigation [ Test Well [ Other (4) TYPE OF WORK: Owner's number of well (if more than one).... New well 石 Method: Dug 日 Bored [ Deepened Driven [ Reconditioned [ Jetted [] Diameter of well 8 (5) DIMENSIONS: Drilled 552 It. Depth of completed well 22 (6) CONSTRUCTION DETAILS: Casing installed: 12 " Diam. from 0 ft. to 50 ft. 8" Diam, from ±2 ft. to 552 ft. " Diam. from \_\_\_\_\_ ft. to \_\_\_\_ ft. K Dester Perforations: Yes 점 No [] ster Type of periorator used\_\_\_\_ SIZE of perforations \_\_\_\_\_\_ in. by \_\_\_\_\_\_\_\_ \_ ft. \_\_\_\_ perforations from \_ . ft. to \_ Screens: Yes [] No.[] Manufacturer's Name.... \_ Model No\_\_\_\_ Diam. \_\_\_\_ Slot size \_\_\_\_ from \_\_\_\_ ft. to \_ \_\_ Slot size \_\_\_\_ from \_\_\_ wravel packed: Yes | No M Size of gravel: ... Gravel placed from \_\_\_\_\_ ft. to ...\_\_\_\_ Surface seal: Yes No D To what depth? \_56\_\_ Material used in seal Neat cement Did any strata contain unusable water? Type of water? \_\_\_\_\_ Depth of strata .\_\_\_\_ Method of sealing strata off.... (7) PUMP: Manufacturer's Name Tait Type: \_\_Verticle Turhine\_\_ 1765 Land-surface elevation (8) WATER LEVELS: Static level 16 tt. below top of well Date 9/26/75 \_Ibs. per square inch Date\_\_\_\_ Artesian pressure \_\_ Artesian water is controlled by..... (Cap, valve, etc.)

(10) WELL LOG:

Formation: Describe by color, character, size of material and structure, and show thickness of equifers and the kind and nature of the material in each stratum penatrated, with at least one entry for each change of formation. MATERIAL FROM too soil tan Contlonerate travel & boulders fire 75 gravel & sand med. soft

Address 129 N. Ind St., Yakima, Wa. 98901

- SN 14 SW 14 Sec 27 T-13 N R 18 WM

75 03 Sand gray loose med. to fine 03 52 Conflorerate Fray fire 3: 100 Sandstone with gravel & silt Med s 100 105 105 Conglomerate tan med. firm 115

115 eray hard 2 Eravels sand silt brown sof 129 tan hard 145 b Sand & zravel silted m. sof 147

202 coarse tan heavy silt 202 215 . clay sand s. gravel soft 219 215 tan firm 219 220 t Fravel & sand-clay interbels 220 241

. 241 245 ton hard tan firm-morrow soft strat 245 262 Glev ten with small gravel 3 sent 50262 271 Compacted sall gravel-sand-silt light brown-good water to 271 280

SEN 256 Clay-ton-some grovel-sand coft Con-lowerate ton (licht) red fir 305 Companded sand-small gravel tan li-ht silt (water) 512 FIDE Tornact gravel sand heaver silt 324 tan (w ter) 212

354 551 Condent send-coarse-brown water Clay with sand-tight 552 Valor amafers at 271ft to 280ft

30501 to 32101

Work started 7/16 \_\_\_\_\_, 19.73 ... Completed \_ 9/25 WELL DRILLER'S STATEMENT: hrs. This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

Enseible other unationale marrow lengel

Other noticable lasser acuafers

SOFE to 25ft 100ft to 10 ft

NAME Cassel Well Drilling (Person, firm, or corporation) (Type or print)

1308 Voelker Yakita, Wn. 93902

License No. 0075 Date 9/25/75 19

Baller test 40 gal/min, with 12 ft. drawdown after 1 hrs.

10

Artesian flow \_\_\_\_\_\_\_ g.p.m. Date \_\_\_\_\_\_\_ Temperature of water . 55 Was a chemical analysis nigot? Tes O No O

Drawdown is amount water level is lowered below static level

ft, drawdown after

Time

Was a pump test made? Yes D No D Wyes, by whom OSSBong. \_

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

gal./min. with 50

Time Water Level Time Water Level 2:00 50 2:01.

.... of test 3/12/23\_\_\_

(9) WELL TESTS:

Yield: 600

500

(US\$ ADDITIONAL SHEETS IF NECESSARY)